

Attachment A: Digital Images

Page 1 of 5

May 5th, 2008

BOE Building 19th Floor Men's Rest Room Assessment
Sacramento, CA



- 1) Image of 19th Floor Man's Restroom access door at time of assessment of BOE Building (Subject Building) located at 450 N Street, Sacramento, California.



- 2) Image of JLS representative, Rick Boggs removing center panel to gain visual access to moisture impacted materials at time of preliminary assessment performed on May 1st, 2008.



- 3) Image of panel and cabinet staining present with indications of historic moisture staining present on building materials.



- 4) Close-up image of stained cabinet and sheetrock materials associated with historic moisture release from sink area systems.



- 5) Image of sink cabinet cavity to right of basin area. Similar staining present within cabinet materials.



- 6) Image of area located beneath cabinet where staining is currently present on wood materials located above tile level.



- 7) Close-up image of stained paper and particle board materials present within left side sink cabinet access panel materials.



- 8) Image of left sink cabinet area with minimal staining present on exposed building materials.



- 9) Image of air sampling equipment utilized within men's rest room on May 5th, 2008 to assess potential exposures during normal occupied times.



- 10) Image of second interior airborne sample collected within men's rest room area at time of supplemental assessment performed on May 5th, 2008.